## Message

From: Hanchett, James (DPH) [/O=COMMONWEALTH OF MASSACHUSETTS/OU=MASSMAIL-

01/CN=RECIPIENTS/CN=JAMES.HANCHETT]

**Sent**: 2/27/2012 3:12:03 PM

To: 'Lobik Stephen' [slobik@facil.umass.edu]

Subject: RE: AC/Heating Unit

They increased steam pressure. That seamed to quite it down for a while. We will place another work order with PP.

Thanks,

Jim

From: Lobik Stephen [mailto:slobik@facil.umass.edu]

Sent: Monday, February 27, 2012 9:46 AM

**To:** Hanchett, James (DPH)

Cc: Pocsik Mark

Subject: RE: AC/Heating Unit

Jim,

At this point neither contractor is responsible. The work is guaranteed for 1 year from acceptance then Physical Plant take over the maintenance. If you call the PP service desk they should send someone out to make the repair. What did PP do the last time they came out?

## Stephen

Stephen Lobik
Capital Project Manager
Facilities Planning Division
University of Massachusetts
(T) 413-545-6516

(C)

(F) 413-545-3684 slobik@facil.umass.edu

From: Hanchett, James (DPH) [mailto:james.hanchett@state.ma.us]

Sent: Monday, February 27, 2012 9:31 AM

**To:** Lobik Stephen **Subject:** AC/Heating Unit

Hi Steve,

The noise is back with a vengeance. It must be outside temperature dependent. Could you see if the contactor who installed it is responsible or is Johnson Controls?

Thanks,

## Jim Hanchett

Amherst Drug Lab Room N251 Morrill I 637 North Pleasant Street Amherst, MA 01003 Phone 413-545-2607 Fax 413-545-2608 Cell